DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-011588 Address: 333 Burma Road **Date Inspected:** 16-Jan-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Mr.Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girder(OBG)Component

Summary of Items Observed:

This CALTRANS OSM Quality Assurance Inspector (QA) Surendra Prabhu was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG TRIAL ASSEMBLY

This QA inspector performed T-Rib dimensional survey and recorded horizontal and vertical offset along with QA inspector Mr. Manoj Prabhune for below segment. Reports forwarded to team leader for further action. 6BW -6CW.

This QA Inspector observed the following work in progress:

SEGMENT:7AE-7BE

Flux Cored Arc Welding (FCAW) welding of weld joint BP116-001-037. Welder is identified as 220067. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by CWI appeared to comply with the Applicable WPS: WPS-B-T-2233-B-U2-F.

SEGMENT: CB-5

Flux Cored Arc Welding (FCAW) welding of weld joint CB202A-005-003. Welder is identified as 066283. ZPMC Quality Control (QC) is identified as Mr.Feng Ya Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2232-TC-U4b-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SEGMENT:6BW-6CW

Shielded Metal Arc Welding (SMAW) welding of weld joint EP041-001-013. Welder is identified as 066261. ZPMC Quality Control (QC) is identified as Mr.Feng Ya Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2214-B-U2-FCM-1.

SEGMENT:6AE

Shielded Metal Arc Welding (SMAW) welding of weld joint SSD18-PP-039-169. Welder is identified as 067261. ZPMC Quality Control (QC) is identified as Mr.Zhang Xiao Ming. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2214-B-U4b-FCM-1.

SEGMENT:6CW

Shielded Metal Arc Welding (SMAW) welding of weld joint OBW6C -003. Welder is identified as 066261. ZPMC Quality Control (QC) is identified as Mr.Feng Ya Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2214-B-U2-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and Quality Control (QC) concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Prabhu,Surendra	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer